

Optical Techniques, Inc.

NEWTOWN INDUSTRIAL COMMONS
205 PHEASANT RUN
NEWTOWN, PA. 18940

NOTICE!

Before taking out any components, note the orientation of all foam blocks and packing cushions. If for any reason you ever have to send any unit back to our plant or ship it anywhere, always replace all packing supports just as you found them.

Close attention to this procedure remains important to help prevent damage to the case or its contents during shipment. For normal handling and transport while you use the instrument, you may omit the extra blocks and cushions and store them inside the shipping carton for safekeeping.